


The information disclosed herein is the property of the originator who reserves all patent, design, proprietary, manufacturing, use and sales rights thereto, except for the rights expressly granted to others. This document shall not be reproduced nor shall the information contained within be used by or disclosed to others except as expressly authorized by the originator. ©

Revision
Letter

Change
Description



Assembly Instructions:

1. PreCut 107 7/8" lengths of 1/8" Diameter, 7x19 Galvanized Control Cable
2. Thread 40" length of Poly Tubing onto Cable.
3. Insert one end of Cable into MS20667-4 Fork End so Cable end is even with the inside radius of the fork.
4. Verify that 1/8" Swage Tooling is installed in Cable Swager
5. Swage MS Eye End onto Cable
6. Rotate MS Eye End 90 degrees and Swage MS End onto Cable a second time.
7. Pull Strongly against the Swage to verify Cable is securely swaged.
8. Sting Cable through one side of the 18-3M Nicopress Sleeve and loop it back into the other side.
9. Place AN100-4 Thimble into the loop formed by the cable and pull the cable tightly against the Thimble.
10. Make sure the cable is protruding 1/16" out from the nicopress sleeve and swage nicopress 3 times. Once on each side and then in the center.
11. Package Qty 2 Assemblies per bag along with Qty 2 WIX-C04-03 and place part label inside bag. Put on shelf for shipment.

SAME AS XNS-C04-02

Sonex Aircraft, LLC

Wailex Forward Rudder Cables

Drawing Scale

FULL

Drawing Number

WIX-C04-01

Revision

N/C